

Post Mobilization Technical Support

H₂S Leakage Mock Drill Conducted at Kesanapalli (West) GGS

Last Updated on:-

Apr 28 th, 2025

Brief details:

An H₂S Leakage Mock Drill was conducted on **28.04.2025 at 17:16:45 hrs** at the **Old ETP Effluent Discharge Manifold Area** in **Surface Installation Area-1, Kesanapalli (West) GGS**. The drill simulated a hydrogen sulfide gas leakage scenario to assess emergency preparedness and response effectiveness.

The mock drill was conducted by **Mr. Dabbiru Hardhik Pattnaik, Installation Safety Officer, CORE-EHS Solutions Pvt. Ltd.** The exercise focused on early detection of H₂S leakage, safe evacuation procedures, use of personal protective equipment, and coordination among response teams. The drill reinforced adherence to safety protocols and enhanced readiness to manage H₂S-related emergencies effectively.

Images:







his accomplishment represents a major step toward developing a capable workforce ready to greatly influence the successful implementation of Lakshya